

STEREO MOC Status Report  
Time Period: 2008:063 - 2008:069

STEREO Ahead (STA) Status:

1. The following Ground System anomalies occurred during this reporting period:

- On day 069, DSS 25 transmitter tripped off-line at 1349Z for 20 minutes. This resulted in a small amount of SECCHI data loss due to resweeping the uplink and a loss of 20 minutes of tracking data. See DR# G108410 for more information.

2. Ahead spacecraft performance continues to be very good with all subsystems performing nominally. The following spacecraft/instrument events occurred during this week:

- The average daily SSR playback volume for Ahead was 7.1 Gbits during this week.

STEREO Behind (STB) Status:

1. The following Ground System anomalies occurred during this reporting period:

- None.

2. Behind spacecraft performance continues to be very good with all subsystems performing nominally. The following spacecraft/instrument events occurred during this week:

- On DOY 063, PLASTIC flight software was updated to version 3.2.7.
- The average daily SSR playback volume for Behind was 7.4 Gbits during this week.